

CEM

DT-3386 CLAMP METER



Professional Heavy Duty 1000 Amp / Volt AC/DC Clamp Meter

50,000 Count

An easy to see large backlit display

True RMS measurement for AC Volts & AC Amps

NCV detection plus built-in flashlight

Double moulded plastic housing

Flexible current probe expands the measurement range to 3000 A AC

Functions

AC/DC Current measurement; AC True RMS; 50000 counts LCD display; Backlight; Built in flashlight; 3000A ACA flexible clamp; Data Hold & Peak Hold; Max /Min; REL (Zero) function; Auto power off; Low battery indication; 48mm Jaw opening; NCV Detection

Specifications

Function	Max Range	Basic Accuracy
Voltage DC	1000V	±(0.1%+4d)
Voltage AC	1000V	±(1.0%+3d)
Current DC	1000.0A	±(2.5%+5d)
Current AC	1000.0A	±(2.5%+5d)
Resistance	50MΩ	±(3.0%+5d)
Temperature	1000°C	±(1.0%+2.5°C)
Capacitance	5mF	±(3.5%+10d)
Frequency	10MHz	±(0.3%+2d)
ACA flexible clamp	3000A	±(2.8%+8d)
Continuity check	Buzzer sounds at 50Ω	
Diode test	Test current 0.3mA	